DEPARTMENT OF

ENVIRONMENTAL MANAGEMENT

INDIANAPOLIS, 46225

105 South Meridian Street

July 7, 1986

Mr. Paul Fuller
Design and Manufacturing Corporation
2000 Illinois Avenue
Connersville, IN 47331

Dear Mr. Fuller:



Re: RCRA Generator Inspection
Design and Manufacturing Corporation
Absocold Corporation
IND 087032207
Notice of Compliance (V-287)

Based upon documents available to Solid and Hazardous Waste Management staff during a record review on June 12, 1986, it has been determined that Design and Manufacturing Corporation-Absocold Corporation has achieved compliance with the terms of the Notice of Violation issued on March 17, 1986.

If you have any questions regarding this matter, feel free to contact Mr. Dennis Zawodni of the Office of Solid and Hazardous Waste Management, Department of Environmental Management, at AC 317/232-3407.

David D. Lamm

Assistant Commissioner for

Solid and Hazardous Waste Management

DMZ/1sm

cc: Wayne County Health Department

Ms. Sally Swanson, U.S. EPA, Region V Mr. Randy Kincaid, Sanyo Corporation

Mr. Bruce Kizer

1Ba



CONNERSVILLE, IND.

Telephone: (317) 825-3181

FAX Number: 317-827-0426

March 24, 1986

Mr. Dennis Zawodni Indiana State Board of Health Division of Land Pollution Control 1330 West Michigan Street P. O. Box 1964 Indianapolis, Indiana 46206-1984

RE: RCRA Generator Inspection Violation (V-287)

Dear Mr. Zawodni:

Since the inspection of our Richmond D & M and Absocold plant was made on January 23, 1986, Design and Manufacturing has sold these buildings and grounds to Sanyo E & E of Japan. As of the first of March 1986, Sanyo now has complete control of these buildings and grounds. We will be unable to make any changes or corrective action at the Richmond plant.

I would like to respond to the violations listed and actions that were taken, or are being taken, relative to the Connersville plant.

Violation #1: Generator has not determined if the nickel filter sludge from the iron and zinc phosphate tanks is hazardous.

The nickel filter sludge is developed by the replacement of iron with nickel on the ware going through a pickling operation. This sludge is made up of iron and filter aid material. We are sending a sample for lab analysis to determine if this sludge is hazardous.

Violation #2: Manifest do not contain a unique five-digit manifest document number.

This five-digit number was started with our next shipment February 27, 1986. It is understood that the State Board will send us the manifest, that will be numbered, to be used.